



Model EJA Series HART Protocol

IM 01C22T01-01E

vigilantplant[®]



CONTENTS

PR	IMINARY	. ii
1.	ERO POINT ADJUSTMENT	-1
	1 1 Zero Point Adjustment	1_1
	1 1 1 Using the HART Communicator	1-2
	1.1.2 Using the Transmitter Zero-adjustment Screw	1-2
	1.2 Auto LRV (Change Low Range Value)	1_2
	1.2.1 Using Model 275 — Apply Values	1_3
	1.2.2 Setting the Range Using the Range-setting Switch	1-3
2.	ART COMMUNICATOR OPERATION	2-1
	2.1 Conditions of Communication Line	2-1
	2.1.1 Interconnection Between DPharp and HART Communicator	2-1
	2.1.2 Communication Line Requirements	2-1
	2.2. Basic Operation of the HART Communicator (Model 275)	2-2
	2.2.1 Keys and Functions	2-2
	2.2.1 Regional and Choice $2.2.2$ Display	2-2
	2.2.2 Display	2-3
	2.2.4 Entering Setting and Sending Data	2-J 2-1
	2.2.4 Entening, Setting, and Sending Data	2-4 2 5
	2.2.1 December Lloga and Selection	2-0
		2-0 2 6
	2.3.2 Method Tree	2-0
	(1) Tag No	2-1 0 7
	(1) Tay No	2-1 2-7
	(2) Chit	2-7
	(4) Output Mode (Linear/Sg root)	2-8
	(5) Damping Time Constants	2-9
	(6) Output Signal Low Cut Mode Setup	2-9
	(7) Bi-directional Flow Measurement	-10
	(8) Change Output Limits	-10
	(9) Integral Indicator Display Mode 2-	-10
	(10) Integral Indicator Scale 2-	-10
	(11) Unit for Displayed Temperature	-12
	(12) Unit for Displayed Static Pressure	-12
	(13) Test Output	-13
	(14) Sensor Irim	-13
	(15) Irim Analog Output	-14
	(10) Burst Mode	10
	(17) Multiarop Mode	-17
	(10) External Switch Node	-17 -18
	(19) Software Write Protect and Burnout Direction	10
	(with Optional code /F1) 2-	-19
	(21) H ₂ O Unit Select	-19
	2.4 Self-Diagnostics	-20
	2.4.1 Checking for Problems	-20
	(1) Identify Problems with HART Communicator	-20
	(2) Checking with Integral Indicator	-21
3.	ARAMETER LISTS	8-1

REVISION RECORD

PRELIMINARY

This manual describes the function, performance, and operating procedures of the DPharp EJA Series with HART protocol. The DPharp EJA Series with HART protocol uses the same pressure sensing element as in DPharp EJA with BRAIN protocol. Therefore, this manual describes only the functions unique to HART Communicator operating procedures which are not covered in the DPharp EJA with BRAIN protocol instruction manual. For the items listed below which are common to both the HART protocol and BRAIN protocol, see the applicable user's manuals listed in Table 1.

Contents of	f Individual	User's	Manuals
-------------	--------------	--------	---------

INTRODUCTION HANDLING CAUTIONS COMPONENT NAMES INSTALLATION INSTALLING IMPULSE PIPING WIRING OPERATION Zero Point Adjustment (For BRAIN Protocol) BRAIN TERMINAL BT200 OPERATION (For BRAIN Protocol) MAINTENANCE PARAMETER SUMMARY (For BRAIN Protocol) GENERAL SPECIFICATIONS Contents of this User's Manual for HART Protocol —IM 01C22T01-01E—		
ZERO POINT ADJUSTMENT HART Communicator OPERATION PARAMETER LISTS		

F01.EPS

Figure 1. Relationship between Individual Manuals and HART Manual Contents

Table 1. Individual User's Manuals

Model	Manual No.
EJA110A, EJA120A, EJA130A	IM 01C21B01-01E
EJA210A, EJA220A	IM 01C21C01-01E
EJA310A, EJA430A, EJA440A	IM 01C21D01-01E
EJA510A, EJA530A	IM 01C21F01-01E
EJA110, EJA120	IM 01C22B01-01E
EJA210, EJA220	IM 01C22C01-01E
EJA310, EJA430	IM 01C22D01-01E
EJA118W, EJA118N, EJA118Y	IM 01C22H01-01E
EJA438W, EJA438N	IM 01C22J01-01E
EJA115	IM 01C22K01-01E

T01.EPS

Matching of communicator DD and instrument DD Before using model 275 HART communicator, check that the DD(Device Description) installed in the communicator matches to that of instruments to set up. To check the DD in the instrument or the HART communicator, follow the steps below. If the correct DD is not installed in the communicator, you must upgrade the DD at the HART official programming sites. For communication tools other than Model 275 HART communicator, contact vendors of each for upgrade information.

- 1. Checking the DD in the instrument
 - 1) Connect the communicator to the instrument to set up.
 - 2) Call "Device setup" and press $[\rightarrow]$.
 - 3) Call "Review" and press $[\rightarrow]$.
 - 4) By pressing [NEXT] or [PREV], find "Fld dev rev" to show the DD of the instrument.

[Example]

Review Fld d 2	/ lev rev		
HELP	PREV	NEXT	EXIT

"The instrument DD is Version 2."

F02.EPS

- 2. Checking the DD in Model 275 HART communicator
 - 1) Turn on the communicator alone.
 - 2) Call "Utility" from main menu and press $[\rightarrow]$.
 - 3) Call "Simulation" and press $[\rightarrow]$.
 - Select "YOKOGAWA" from manufacturers list by pressing [↓] and press [→].
 - Select the model name of the instrument(i.e. EJA) by pressing [↓] and press [→] to show the DD of the communicator.





1. ZERO POINT ADJUSTMENT

After operating preparation is completed, adjust the zero point. The zero point adjustment can be made using either of the following two methods.

For output signal checking, display the parameter **% rnge** in the HART Communicator.



Using the Transmitter Zero-adjustment Screw

Before using the zero-adjustment screw outside the transmitter case, confirm the following.

- **Ext SW mode** must be **ENABLE**. See Subsection 2.3.3 (17) for the setting procedure.
- Use a slotted screwdriver to turn the zero-adjustment screw. Turn the screw clockwise to increase the output or counterclockwise to decrease the output, the zero point adjustment can be adjusted with a resolution of 0.01% of the setting range. The degree of zero adjustments varies with the screw turning speed. Therefore, turn the screw slowly for fine adjustment and quickly for coarse adjustment.

Do not turn off the power to the transmitter immediately after a zero adjustment. Powering off within 30 seconds after a zero adjustment will return the adjustment back to the previous settings.

■ Using the HART Communicator

Zero point can be adjusted by simple key operation of the HART Communicator.

Select parameter **Zero Trim**, and press the **OK (F4)** key twice. The zero point will be adjusted automatically to the output signal 0% (4 mA DC). Confirm that the setting value displayed for the parameter **% rnge** is **0.0%** before pressing the **OK (F4)** key. See Subsection for HART Communicator operating procedures.

1.1 Zero Point Adjustment

The DPharp supports several adjustment methods.

Select the method best suited for conditions matching the state of the site.

Note that output signal can be checked by HART Communicator.

Adjustment Method	Desc	ription
Zero adjustment using the HART Communicator	Set the present input to 0%. P.1-2 'Zero trim'	Adjust for 0% output at input level of 0%.
	Adjust output to the reference value obtained using other means. P.1-2 'Lower sensor trim'	If the input level cannot easily be made 0% (because of tank level, etc.), adjust output to the reference value obtained using other means, such as a glass gauge.
Zero adjustment using the external zero- adjustment screw	 Adjust zero point using the zero- adjustment screw on the transmitter. This permits zero adjustment withou using the HART Communicator. Accurately adjust the output current 4mA DC or other target output value using an ammeter that accurately re output currents. 	

T0101.EPS

1.1.1 Using the HART Communicator

(1) Zeroing — Zero trim

🖄 ΝΟΤΕ

Zero trim carries out the zero adjustment and sets the input values at present, equal to 0 mmH₂O. Use this setting to set LRV = 0 mmH₂O.



(2) Arbitrary Level Adjustment — Lower Sensor Trim

This zero adjustment applies to tank level measurements, etc. where the actual tank level cannot be set to zero. For this adjustment, use the actual tank level obtained with a glass gauge or the like to meet the DPharp output.





🖄 ΝΟΤΕ

Lower Sensor trim adjusts the input value at present. See Fine Input Adjustment for detail.

1.1.2 Using the Transmitter Zero-adjustment Screw

Turn the zero-adjustment screw on the outside of the transmitter case using a slotted screwdriver. Turn the screw to the right to increase the zero point or to the left to decrease the zero output; the zero adjusts in increments of 0.01% of the range setting.

Note that the amount of adjustment to the zero point changes according to the speed at which the screw is turned. To make fine adjustments, turn the screw slowly; to make coarse adjustments, turn the screw quickly.

Note: When a zero point adjustment has been made do not turn of the transmitter less than 30 seconds after adjustment.

1.2 Auto LRV (Change Low Range Value)

1.2.1 Using Model 275 — Apply Values

Display the Apply Values display, and adjust the zero point as follows:



1.2.2 Setting the Range Using the Rangesetting Switch

With actual pressure(s) being applied to the transmitter, the range-setting switch (push-button) attached to the integral indicator plate and the external zero-adjustment screw allow users to change the lower- and upper-range values for the measurement range (LRV and URV) without the use of a HART Communicator. However, a change in the display settings (scale range and engineering unit) for the integral indicator requires a HART Communicator.

Follow the procedure below to change the LRV and URV settings.

Example: Rerange LRV to 0 and HRV to 20 kPa.

- 1) Connect the transmitter and allow them to warm up for at least five minutes.
- Press the range-setting push-button. The integral indicator then displays LSET.
- 3) Apply a pressure of 0 kPa (atmospheric pressure) to the high-pressure side of the transmitter. ^(Note 1)
- 4) Turn the external zero-adjustment screw (either in the output-increase or -decrease direction). The integral indicator displays the output signal (in %). (Note 2)
- 5) Adjust the output signal to 0% (1 V DC) by rotating the external zero-adjustment screw. Doing so completes the LRV setting.
- Press the range-setting pushbutton. The integral indicator then displays USET.
- 7) Apply a pressure of 20 kPa to the high-pressure side of the transmitter. ^(Note 1)
- 8) Turn the external zero-adjustment screw (either in the output-increase or -decrease direction).
 The integral indicator displays the output signal (in %). ^(Note 2)
- Adjust the output signal to 100% (5 V DC) by rotating the external zero-adjustment screw. Doing so completes the URV setting.
- 10)Press the range-setting pushbutton. The transmitter then switches back to the normal operation mode while maintaining the measurement range at 0 to 20 kPa.
- Note 1: Wait until the pressure inside the pressure-detector section has stabilized before proceeding to the next step.
- Note 2: If the pressure applied to the transmitter exceeds the previous LRV (or URV), the integral indicator may display error number "**Er.07**" (In this case, the output signal percent and "**Er.07**" are displayed alternately every two seconds). Although "Er.07" is displayed, there is no need to worry and you may proceed to the next step. However, should any other error number be displayed, take the appropriate measure in reference to Section 2.4 Self-Diagnostics, "Errors Messages."

IMPORTANT

- 1. Do not turn off the power to the transmitter immediately after completion of the change in the LRV (and/or URV) setting(s). Note that powering off within thirty seconds after setting will ca use a return to the previous settings.
- 2. Changing LRV automatically changes URV to the following value.

URV = previous URV + (new LRV - previous LRV)

3. If the range-setting push-button and external zero-adjustment screw are not touched during a range-change operation, the transmitter automatically switches back to the normal operation mode.



F0106.EPS

Figure 1.2.1 Range-setting Switch

setting push-button.

2. HART COMMUNICATOR OPERATION

2.1 Conditions of Communication Line

2.1.1 Interconnection Between DPharp and HART Communicator

The HART Communicator can interface with the transmitter from the control room, the transmitter site, or any other wiring termination point in the loop, provided there is a minimum of 250 Ω between the connection and the power supply. To communicate, it must be connected in parallel with the transmitter; the connections are non-polarized. Figure 2.1.1 illustrates the wiring connections for direct interface at the transmitter site for the DPharp. The HART Communicator can be used for remote access from any terminal strip as well.

Control room Relaying terminal board or Distributor DPharp DPharp HART communicator HART communicator

Figure 2.1.1 Interconnection Diagram

2.1.2 Communication Line Requirements

Specifications for Communication Line:

- Supply voltage(general use type); 16.4 to 42 V DC Load resistance; 250 to 600 W (Including cable resistance)
- Minimum cable size; 24 AWG, (0.51 mm diameter) Cable type; Single pair shielded or multiple pair with overall shield

Maximum twisted-pair length; 10,000 ft (3,048 m) Maximum multiple twisted-pair length; 5,000 ft (1,524 m)

Use the following formula to determine cable length for a specific application;

$$L = \frac{.65 \times 10^6}{(R \times C)} - \frac{(C_f + 10,000)}{C}$$

Where: L =length in feet or meters.

- R = resistance in ohms, current sense resistance plus barrier resistance.
- C = cable capacitance in pF/ft, or pF/m.
- $C_f = Maximum shunt capacitance of field devices in pF.$

2.2 Basic Operation of the HART Communicator (Model 275)

2.2.1 Keys and Functions



Figure 2.2.1 The HART Communicator

2.2.2 Display

The HART communicator searches for a transmitter on the 4 to 20mA loop when it is turned on. When the HART communicator is connected to the transmitter, **Online** menu (Top menu) is started automatically and the following display appears. If no transmitter is found, you select **Online** menu.



Figure 2.2.2 Display

- <a>) appears and flashes during communication between the HART communicator and the transmitter. At Burst mode, **W** appears.
- The menu items selected from the previous menu.

<c> The items to be used from the menu of .

- <d> \uparrow or \downarrow appears when the item is scrolled out of the display.
- <e> The labels of function corresponding to each function key appears. These labels reflect currently available choices.

2.2.3 Calling Up Menu Addresses

Subsection 2.3.2 shows the configuration of all menu items available with the HART communicator. The desired item can be displayed with ease by understanding the menu configuration.

When the HART communicator is connected to the transmitter, **Online** menu will be displayed after power is turned on. Call up the desired item as follows:

Function Key Labels

	F1	F2	F3	F4
,	HELP access on-line help	ON/OFF activates or deactivates a binary variable	ABORT terminate current task	OK acknowledge information on screen
RETRY try to re- establish communication		DEL delete current character or Hot Key Menu item	ESC leave value unchanged	ENTER accept user- entered data
	EXIT leave the current menu	SEND send data to device, or mark data to send	QUIT terminate session because of a comunication error	NEXT leave the current menu
у	YES answer to res/no question	PGUP move up one help screen	PGDN move down one help screen	NO answer to yes/no question
i	ALL nclude current lot Key item on Hot Key Menu for all devices	PREV go to previous message in a list of messages	NEXT go to next message in the list of messages	SKIP do not mark variable to be sent in off-line configuration
	SAVE save informatior to	EDIT edit a variable value	HOME go to the top menu in the device description	ONE include Hot Key item for one device
	communicator SEND send data to device, or mark data to send	ADD add current item to Hot Key Menu	BACK go back to menu from which HOME was pressed	E0204 FD2

Key Operation

There are two choices to select the desired menu item.

- 2. Press the number displayed for the desired item.
- To return to the previous display, press the 🔁 key.
 - * If ABORT, ESC and EXIT are displayed, press the desired function key.

Example: Call up the Tag item, to change the tag.

Check to see where item **Tag** is located in the menu configuration. Then, call up **Tag** item on the display according to the menu configuration.





2.2.4 Entering, Setting, and Sending Data

The data input using the keys are set in the HART communicator by pressing **ENTER (F4)**. Then, by pressing **SEND (F2)**, the data is sent to the transmitter. Note that the data is not set in the transmitter if **SEND (F2)** is not pressed. All the data set with the HART communicator is held in memory unless power is turned off, every data can be sent to the transmitter at once.

Operation

Entering data on the Tag setting display.

Example: To change from Tag YOKOGAWA to FIC-1A.

Call up the **Tag** setting display.



When the setting display shown above appears, enter the data as follows:



Display	Operation
5 EJA:YOKOGAWA Tag YOKOGAWA FIC-IA HELP DEL ESC ENTER	(ENTER) After entering the data, set the HART communicator with the data entered by pressing ENTER (F4) .
6 EJA:YOKOGAWA Basic setup 1 Tag 2 Unit 3 Re-range 4 Device information 5 Xfer fncth HELP SEND HOME	(SEND) Send the data to the transmitter by pressing SEND (F2) .
7 EJA:FIC-1A Basic Setup 1 Tag 2 Unit 3 Re-range 4 Device information 5 Xfer fncth HELP HOME	* () is flashed during communica- tion. SEND disappears, and the transmission is complete.
	E0208.EPS

2.3 Parameters

2.3.1 Parameter Usage and Selection

Before describing the procedure for setting parameters, we present the following table showing how the prameters are used and in what case.

🖄 ΝΟΤΕ

Do not turn off the transmitter as soon as HART Communicator settings (sending) have been made. If the transmitter is turned of less than 30 seconds after parameters have been set, the set data will not be stored and the terminal returns to previous settings.

Table 2	2.3.1	Parameter	Usage	and	Selection

Image: state	Item		HART Communicator	Description	Page
Image is a set of the second of th	Memory		Tag	Tag number, Up to 8 characters	
<table-container> Image is a start of a start of</table-container>			Descriptor	Up to 16 characters	
Transmitter Engle xxylyzz xxylyzz Profestional option of the prof			Message	Up to 32 characters	
Image in the second s			Date	xx/yy/zz	P.2-7
Range LINURY Set the calination range by the keyad Hermitian Apply values Range for 4 b 20 mADE signals at with actual input applied. Perfect Duply mode Mar finds Range for 4 b 20 mADE signals at with actual input applied. Perfect Duply mode Mar finds Range for 4 b 20 mADE signals at with actual input applied. Perfect Duply signal low cal Dup of an input applied. Range for 4 b 20 mADE signals at with actual input applied. Perfect Bedreection flow Mar and the actual response predict of a 20 mA DE c. 20, 51, 15, 24, 48, 69, 69 Perfect Had units able con Hour of the actual response predict of a 20 mA DE c. 20, 51, 15, 24, 48, 69, 69 Perfect Had units able con Hour of the actual response predict of a 20 mA DE c. 20, 51, 15, 24, 48, 69, 69 Perfect Had units able con Hour of the actual response predict of a 20 mA DE conset. Perfect Had units able con Hour of the actual response predict of a 20 mA DE conset. Perfect Had units able con Bale presen Set and for fampal indicator to finand and the presence display and attermet indicator to finand and the sponse presence display and attermet indicator of action and the sponse presence display and atteremet actace indicator' response fampal andicator of actace andi	Transmitter	Engineering unit	Unit	inH ₂ O, inHG, ftH ₂ O, mmH ₂ O, mmHG, psi, bar, mbar, g/cm ² , kg/cm ² , Pa, kPa, MPa, torr, atm	
Image Image <t< td=""><td></td><td>Range</td><td>LRV/URV</td><td>Set the calibration range by the keypad</td><td></td></t<>		Range	LRV/URV	Set the calibration range by the keypad	
Quput mode Xer facts Sets mode for output signal to "intear mode" (proportional to input differential pressure) P2-8 Damping time constant Damp Adjust the output response speed for 4 to 20 mA DC. 0.2, 0.5, 1, 1.5, 2, 4, 6, 8, 16, 32 P2-9 Output aginal low cut Low cut Used mainly to stabilize output near 0 if output signals is the square nort mode. Two mode are available for input below a specific value. P2-9 Bi-diraction flow measure bi-directional flows. Diractional to the constant incode P2-10 Bi-diraction flow measure bi-directional flows. P2-10 P2-10 Unit for displayed static Bi-diraction flow measure bi-directional flows. P2-11 Unit for displayed static State pressure State pressure P2-12 Unit for displayed static State pressure State pressure State mode for integral indicator indicator insplay P2-12 Display Integral indicator display State pressure in the static pressure displayed on the model 275. P2-11 Integral indicator display State pressure onto mode (reprodutinat for low in the state pressure displayed on the model 275. P2-12 Integral indicator display State pressure onto measure onto mode (reprodutinat fonow). P2-10			Apply values	Range for 4 to 20 mA DC signal is set with actual input applied.	
Imaging time constant Damp digits the output response specified 16 20 mADC. 0.2, 0.5, 1, 1.5, 2, 4, 6, 8, 6, 8, 9, 9, 9, 9, 9, 9, 9, 9, 9, 9, 9, 9, 9,		Output mode	Xfer fnctn	Sets mode for output signal to "linear mode" (proportional to input differential pressure) or to "Square root mode" (proportional to flow).	P.2-8
Output signal word mode Low out Used mainly to stabilize output near 01 in uppt signals the square not mode. Two proprior and uppt for proprior autput for input below a specific value. Proprior Proprice Proprior Proprior Proprior Proprior Proprior Propr		Damping time constant	Damp	Adjust the output response speed for 4 to 20 mA DC. 0.2, 0.5, 1, 1.5, 2, 4, 6, 8, 16, 32 (sec)	
Integral indicator scale Gut mode Linear or Zero Procession Hold indicator scale B-drie mode Used to measure bidirectional flows. P.2-10 Hyb units election Hyb Unit selection at 4°C (33.2°F)/at 20°C (66°F) P.2-10 Init for displayed static Sens remp unit Sets a unit for temperature displayed on the model 275. P2-12 Display Integral indicator scale Sets mode for integral indicator for linear mode' (proportional to input differential pressure) or to "Square root mode' (proportional to fow). P2-10 Display Integral indicator scale indicator scale indicator, "alternate indicator, "alternate indicator or linear mode' (proportional to fow). P2-11 HART output Burst option Set for following 5 types of integral indicator scale and % scale and % scale indicator). P2-11 Hutt-drop mode Burst option Set for of multi-drop mode. P2-11 Multi-drop mode Pers S Pers We display and "alternate indicator on linear mode" (proportional to now). P2-16 Multi-drop mode Pers S Set for display and "alternate indicator on linear mode" (proportional to now). P2-16 Sint or mode Set mode Set or tonor the data to be sent continuously (Pres/% mige/A01 out		Output signal low cut mode	Low cut	Used mainly to stabilize output near 0 if output signal is the square root mode. Two mode are available: forcing output to 0% for input below a specific value, or changing to proportional output for input below a specific value.	P.2-9
Bi-direction flow measurement model Bi-dire model Used to measure bi-directional flows. P2-10 H_0 Unit selection H_0 Unit selection H_0 Unit selection 41°C (39.2*F)/at 20°C (88°F) P2-19 Unit for displayed imperature Sars temp unit Sets a unit for temperature displayed on the model 275. P2-12 Display Integral indicator display Salic press unit Sets a unit for static pressure displayed on the model 275. P2-10 Display Integral indicator display Display form Sets mode for integral indicator on "incer mode" (proportional to flow). P2-10 Display Integral indicator display Display mode Sets mode for integral indicator on display on disp orint. P2-10 Marce Engr disp range Engr display diag biophi. Selection of the data to be set continuously (Pres% mge/A101). P2-10 HART outpl Mult-drop mode Poll addr Selection of the data to be set continuously (Pres% mge/A101). P2-11 Mult-drop mode Ford splay odupt variable Selection of the data to be set continuously (Pres% mge/A101). P2-12 Mult-drop mode Ford splay odupt variable Selection of the data to be set continuously (Pres% mge/A101).			Cut mode	Linear or Zero	
H ₂ O unit selection H ₂ O luit select at 4°C (39.2°F)/at 20°C (88°F) P2-19 Unit for displayed temperature Sins temp unit Sets a unit for temperature displayed on the model 275. P2-12 Display Unit for displayed static pressure on the sets and the temperature displayed on the model 275. P2-12 Display Integral indicator display mode Satic pressure in the sets mode for integral indicator to "intear mode" (proportional to input differential pressure) on the Square root mode" (proportional to input differential pressure) and square indicator of square root mode" (proportional to input differential pressure displayed and "alternate indication of user sets cale and % scale". "Input pressure display" and "alternate indicator of input pressure and % scale". "Input pressure display" and "alternate indication of user sets cale and % scale". "Input pressure display" and "alternate indication of user sets cale and % scale". "Input pressure display" and "alternate indication of user sets cale and % scale". "Input pressure display" and "alternate indication of user sets cale and % scale". "Input pressure display" and "alternate indication of user sets cale and % scale". "Input pressure display" and "alternate indication of user sets cale and % scale". "Input pressure display" and "alternate indication"." P2-10 HART output Burst mode ON/OFF switching of burst mode. P2-10 Multi-drop mode P0-11 addr Setting the polling address (1 to 15). Alter pressure and % scale". "Input % output variable Alto 1 output variable <td< td=""><td></td><td>Bi-direction flow measurement mode</td><td>Bi-dire mode</td><td>Used to measure bi-directional flows.</td><td>P.2-10</td></td<>		Bi-direction flow measurement mode	Bi-dire mode	Used to measure bi-directional flows.	P.2-10
Init for displayed imperature imperature pressure Snst temp unit Sets a unit for temperature displayed on the model 275. P-12 Display mode Integral indicator display mode Static press unit Sets a unit for static pressure displayed on the model 275. P-210 Display mode Integral indicator display mode Sets mode for integral indicator to "linear mode" (proportional to input differential pressure) or to "Square root mode" (proportional to flow). P-210 Integral indicator scale Engr disp range Engr display and "alternate indication of input pressure and % scale", "input pressure display" and "alternate indication of input pressure and % scale", "input pressure display" and "alternate indication of input pressure and % scale", "input pressure display" and "alternate indication of input pressure and % scale", "input pressure display" and "alternate indication of input pressure and % scale", "input pressure display" and "alternate indication of input pressure and % scale", "input pressure display" and "alternate indication of input pressure and % scale", "input pressure display display for the data to be sent continuously (Pres/% mge/A01 out). P-2-10 HART output Burst mode Sett pressure variable Mouti-drop mode. P-2-10 Multi-drop mode Fres Pressure variable Moutput variable P-2-10 Monitoring Sett output Loop test Used for loop checks. Output variable P-2-12 <td></td> <td>H₂O unit selection</td> <td>H₂O Unit select</td> <td>at 4°C (39.2°F)/at 20°C (68°F)</td> <td>P.2-19</td>		H ₂ O unit selection	H ₂ O Unit select	at 4°C (39.2°F)/at 20°C (68°F)	P.2-19
Unit or displayed static pressure Static pres unit Sets a unit for static pressure displayed on the model 275. P.2.12 Display mode Integral indicator display mode Display fnoth Sets mode for integral indicator to "linear mode" (proportional to low). P.2.10 Display mode Display mode Sets mode for integral indicator to "linear mode" (proportional to low). P.2.10 Integral indicator scale Engr disp range Engr unit/Engr disp LRV/Engr disp DRV/Engr disp point. P.2.10 HART output Burst mode Burst option Selection of the data to be sent continuously (Pres% mge/A01 out). P.2.10 HART output Burst option Selection of multi-frag disp LRV/Engr disp DRV/Engr disp point. P.2.10 Multi-drop mode Press Pressure variable P.2.10 Auto poll ON/OFF switching of multi-drop mode. P.2.10 Monitoring Pres Pressure variable P.2.10 Salid press Static pressure Static pressure Static pressure Salid press Static press Static pressure Static pressure P.2.12 Maintenzne Test output Loop test Used for l		Unit for displayed temperature	Snsr temp unit	Sets a unit for temperature displayed on the model 275.	5.0.40
Display Integral indicator display mode Display function Sets mode for integral indicator or incer mode" (proportional to input differential pressure) or to "Square root mode" (proportional to flow). P.2-10 Minor Display mode Sets mode for integral indicator scale ranges and unit. "% scale indicator", "pressure or to "Square root mode" (proportional to flow). P.2-10 HART output Integral indicator scale Engr disp range Engr unit/Engr disp LRV/Engr disp URV/Engr disp point. P.2-10 HART output Burst mode Burst option Selection of the data to be sent continuously (Pres% mge/A01 out). P.2-10 Multi-drop mode Poll addr Sets mode for integral indicator or address (1 to 15). P.2-16 Monitoring Static pres Pressure variable Pressure variable P.2-10 Monitoring Static press Static pressure Static pressure P.2-12 Maintenance Test output Loop test Used for loop checks. Output variable P.2-12 Maintenance Test output Loop test Used for loop checks. Output can be set freely from -5% to 10% in 1% step. P.2-12 Maintenance Test output Loop test Used vising the self-lead comm		Unit for displayed static pressure	Static pres unit	Sets a unit for static pressure displayed on the model 275.	P.2-12
bisplay mode Set the following 5 types of integral indicator scale and 9% scale. "Integral indicator", "use set scale indicator", "alternate indication of user set scale and % scale.", "input pressure display" and "alternate indication of input pressure and % scale.", "input pressure display" and "alternate indication of user set scale and % scale.", "input pressure display" and "alternate indication of user set scale and % scale.", "input pressure display" and "alternate indication of user set scale and % scale.", "input pressure display" and "alternate indication of user set scale indicator", "use set scale indicator," and "alternate indication of user set scale and % scale.", "input pressure display" and "alternate indication of user set scale indicator," integral indicator scale and % scale.", "input pressure display" and "alternate indication of user set scale indicator," and "alternate indication of user set scale indicator," integral indicator scale and % scale.", "input pressure display" and "alternate indication of user set scale indicator," integral indicator scale and % scale.", "input pressure display" and "alternate indication of user set scale indicator," integral indicator scale and % scale.", "input pressure display" and "alternate indication of user set scale indicator,", "integral isoparation isoparation of user set scale indicator,", "integral isoparation of user set scale indicator,", "integral isoparation of user set scale indicator,", "integral isoparation,", "integral isoparatit,", "integral isoparation,", "integral isoparation,", "integral i	Display	Integral indicator display mode	Display fnctn	Sets mode for integral indicator to "linear mode" (proportional to input differential pressure) or to "Square root mode" (proportional to flow).	P.2-10
Integral indicator scale Engr disp range Engr unit/Engr disp LRV/Engr disp URV/Engr disp point. P.2.10 HART output Burst mode Burst mode ON/OFF switching of burst mode. Note the polling address (1 to 15). Note the polling address (1 to 15). P.2.10 Monitoring Pres Pres Pressure variable Note the polling address (1 to 15). Note the poling address (1 to 15). Note polling			Display mode	Set the following 5 types of integral indicator scale ranges and unit: "% scale indicator", "use set scale indicator", "alternate indication of user set scale and % scale", "input pressure display" and "alternate indication of input pressure and % scale.	P.2-11
HART output hart mode Burst mode Burst mode Selection of the data to be sent continuously (Pres/% mge/A01 out). New pressure mode Multi-drop mode Poil addr Setting the polling address (1 to 15). Pres Pres Pressure variable Pressure variable </td <td></td> <td>Integral indicator scale</td> <td>Engr disp range</td> <td>Engr unit/Engr disp LRV/Engr disp URV/Engr disp point.</td> <td>P.2-10</td>		Integral indicator scale	Engr disp range	Engr unit/Engr disp LRV/Engr disp URV/Engr disp point.	P.2-10
Image Burst mode ON/OFF switching of burst mode. Presenance Multi-drop mode Poll addr Setting the polling address (1 to 15). Auto poll ON/OFF switching of multi-drop mode. Presenance Monitoring Pres Pressure variable Pressure variable Notper setting and upper trained by the polling address (1 to 15). Pressure variable	HART output	Burst mode	Burst option	Selection of the data to be sent continuously (Pres/% rnge/A01 out).	
Multi-drop mode Poll addr Setting the polling address (1 to 15). Pression of the polling address (1 to 15). Pression of the polling address (1 to 15). Monitoring Press Pressure variable % output variable % output variable Monitoring % inge % output variable % output variable % output variable All out 4 to 20 mA output variable Sins remp Sensor temperature Pressure variable Static press Static press Static pressure Displays output as on an LCD. settable in the engr disp range. Pressure variable Maintenance Test output Loop test Used for loop checks. Output can be set freely from -5% to 110% in 1% step. Pressure variable Maintenance Self-diagnostics Self test Check using the self-test command. If an error is detected, the corresponding message is displayed. Pressure variable Output when CPU error has occurred And Alarm typ Display for the result of self-test, calibration of transmitter. Pressure variable write protect status is released for 100 minutes when the password is entered. Adjustmen External volume protect/permit Ext SW mode Displays the permit/protect status of setting changes depending on communications.			Burst mode	ON/OFF switching of burst mode.	D 2 16
Auto poll ON/OFF switching of multi-drop mode. Monitoring Working With Protect Press Pressure variable No output variable Monitoring Working With Protect % ringe % output variable No output variable Monitoring Working With Protect Monitoring % ringe % output variable No Monitoring With Protect Static press Sensor temperature Sensor temperature No Static press Static pressure Displays output and son an LCD. settable in the engr disp range. P.2-12 Maintenance Test output Loop test Used for loop checks. Output can be set freely from -5% to 110% in 1% step. P.2-13 Maintenance Self-diagnostics Self test Check using the self-test command. If an error is detected, the corresponding message is displayed. P.2-19 Output when CPU error has occurred All Alarm typ Display the tastus of 4 to 20 mA DC output when a failure		Multi-drop mode	Poll addr	Setting the polling address (1 to 15).	F.2-10
Monitoring Monitoring Pres Pressure variable Pr			Auto poll	ON/OFF switching of multi-drop mode.	
% mge % output variable A01 out 4 to 20 mA output variable A01 out 4 to 20 mA output variable Sns remp Sensor temperature Static press Static pressure Engr display Displays output as on an LCD. settable in the engr disp range. P.2-12 Maintenance Self-diagnostics Self test Check using the self-test command. If an error is detected, the corresponding message is displayed. P.2-19 Status Display of the result of self-test, calibration of transmitter. P.2-19 Maintenance A01 Alarm typ Display the status of 4 to 20 mA DC output when a failure	Monitoring		Pres	Pressure variable	
A01 out 4 to 20 mA output variable Snr temp Sensor temperature Static press Static pressure Engr display Displays output as on an LCD. settable in the engr disp range. P.2-12 Maintenance Test output Loop test Used for loop checks. Output can be set freely from -5% to 110% in 1% step. P.2-12 Self-diagnostics Self test Check using the self-test command. If an error is detected, the corresponding message is displayed. P.2-19 Output when CPU error has occurred A01 Alarm typ Display the status of 4 to 20 mA DC output when a failure protect/permit for LRV (URV) setting. External volume protect/permit Ext SW mode Displays the external volume protect/permit for LRV (URV) setting. P.2-17 Software Write Protect Write protect Displays the permit/protect status of setting changes depending on communications. P.2-17 Adjustment Zero ing Zero itim Set the current input value to 0 kPa. P.1-2 Adjustment Zero itim Lower/Upper sensor tim Adjust only measured pressure variable. P.2-13			% rnge	% output variable	1
Sins remp Sensor temperature Sensor temperatu			A01 out	4 to 20 mA output variable	
Static pres Static pressure Engr display Displays output as on an LCD. settable in the engr disp range. P.2-12 Maintenance Test output Loop test Used for loop checks. Output can be set freely from -5% to 110% in 1% step. P.2-12 Self-diagnostics Self test Check using the self-test command. If an error is detected, the corresponding message is displayed. P.2-19 Output when CPU error has occurred A01 Alarm typ Display of the result of self-test, calibration of transmitter. P.2-17 External volume protect/permit Ext SW mode Displays the external volume protect/permit for LRV (URV) setting. P.2-17 Software Write Protect Write protect Displays the permit/protect status of setting changes depending on communications. P.2-17 Adjustment Zeroing Zero trim Set the current input value to 0 kPa. P.1-2 Analog output trim Dixer/Upper sensor trim Adjust only measured pressure variable. P.2-13 Analog output trim D/A trim, Scaled D/A trim Adjust the output value at the points of 4 mA and 20 mA. P.2-14			Snsr temp	Sensor temperature	-
Engr display Displays output as on an LCD. settable in the engr disp range. Percent (Context or the end of t			Static pres	Static pressure	1
Maintenance Test output Loop test Used for loop checks. Output can be set freely from -5% to 110% in 1% step. P.2-12 Self-diagnostics Self test Check using the self-test command. If an error is detected, the corresponding message is displayed. P.2-19 Output when CPU error has occurred A01 Alarm typ Display of the result of self-test, calibration of transmitter. External volume protect/permit Ext SW mode Display set the external volume protect/permit for LRV (URV) setting. Software Write Protect Write protect Displays the permit/protect status of setting changes depending on communications. P.2-17 Adjustment Zeroing Zero trim Set the current input value to 0 kPa. P.1-2 Analog output trim D/A trim, Scaled D/A trim Adjust the output value at the points of 4 mA and 20 mA. P.2-13			Engr display	Displays output as on an LCD. settable in the engr disp range.	
Self-diagnostics Self test Check using the self-test command. If an error is detected, the corresponding message is displayed. P.2-19 Output when CPU error has occurred A01 Alarm typ Display of the result of self-test, calibration of transmitter. External volume protect/permit Ext SW mode Display/set the external volume protect/permit for LRV (URV) setting. Software Write Protect Write protect Displays the permit/protect status of setting changes depending on communications. P.2-17 Adjustment Zeroing Zero trim Set the current input value to 0 kPa. P.1-2 Analog output trim D/A trim, Scaled D/A trim Adjust the output value at the points of 4 mA and 20 mA. P.2-13	Maintenance	Test output	Loop test	Used for loop checks. Output can be set freely from -5% to 110% in 1% step.	P.2-12
Image: status Status Display of the result of self-test, calibration of transmitter. Output when CPU error has occurred A01 Alarm typ Display the status of 4 to 20 mA DC output when a failure		Self-diagnostics	Self test	Check using the self-test command. If an error is detected, the corresponding message is displayed.	P.2-19
Output when CPU error has occurred A01 Alarm typ Display the status of 4 to 20 mA DC output when a failure			Status	Display of the result of self-test, calibration of transmitter.	
External volume protect/permit Ext SW mode Display/set the external volume protect/permit for LRV (URV) setting. P.2-17 Software Write Protect Write protect Displays the permit/protect status of setting changes depending on communications. P.2-17 Enable write Write protect status is released for 10 minutes when the password is entered. P.2-17 Adjustment Zero ing Zero trim Set the current input value to 0 kPa. P.1-2 Sensor trim Lower/Upper sensor trim Adjust only measured pressure variable. P.2-13 Analog output trim D/A trim, Scaled D/A trim Adjust the output value at the points of 4 mA and 20 mA. P.2-14		Output when CPU error has occurred	A01 Alarm typ	Display the status of 4 to 20 mA DC output when a failure	_
Software Write Protect Write protect Displays the permit/protect status of setting changes depending on communications. P.2-17 Enable write Write protect status is released for 10 minutes when the password is entered. P.2-17 Adjustment Zeroing Zero trim Set the current input value to 0 kPa. P.1-2 Sensor trim Lower/Upper sensor trim Adjust only measured pressure variable. P.2-13 Analog output trim D/A trim, Scaled D/A trim Adjust the output value at the points of 4 mA and 20 mA. P.2-14		External volume protect/permit	Ext SW mode	Display/set the external volume protect/permit for LRV (URV) setting.	
Enable write Write protect status is released for 10 minutes when the password is entered. New password Setting a new password. Adjustment Zero ing Zero trim Set the current input value to 0 kPa. P.1-2 Sensor trim Lower/Upper sensor trim Adjust only measured pressure variable. P.2-13 Analog output trim D/A trim, Scaled D/A trim Adjust the output value at the points of 4 mA and 20 mA. P.2-14		Software Write Protect	Write protect	Displays the permit/protect status of setting changes depending on communications.	P.2-17
Image: Mew password Setting a new password. Adjustment Zero ing Zero trim Set the current input value to 0 kPa. P.1-2 Sensor trim Lower/Upper sensor trim Adjust only measured pressure variable. P.2-13 Analog output trim D/A trim, Scaled D/A trim Adjust the output value at the points of 4 mA and 20 mA. P.2-14			Enable write	Write protect status is released for 10 minutes when the password is entered.]
Adjustment Zeroing Zero trim Set the current input value to 0 kPa. P.1-2 Sensor trim Lower/Upper sensor trim Adjust only measured pressure variable. P.2-13 Analog output trim D/A trim, Scaled D/A trim Adjust the output value at the points of 4 mA and 20 mA. P.2-14			New password	Setting a new password.	
Sensor trim Lower/Upper sensor trim Adjust only measured pressure variable. P.2-13 Analog output trim D/A trim, Scaled D/A trim Adjust the output value at the points of 4 mA and 20 mA. P.2-14	Adjustment	Zeroing	Zero trim	Set the current input value to 0 kPa.	P.1-2
Analog output trim D/A trim, Scaled D/A trim Adjust the output value at the points of 4 mA and 20 mA. P.2-14		Sensor trim	Lower/Upper sensor trim	Adjust only measured pressure variable.	P.2-13
		Analog output trim	D/A trim, Scaled D/A trim	Adjust the output value at the points of 4 mA and 20 mA.	P.2-14

2.3.2 Menu Tree



F0209.EPS

2.3.3 Setting Parameters

(1) Tag No.

To change the Tag No., see section 2.2.4 Entering, Setting, and Sending Data.

Up to 8 characters can be set with **Tag**. The maximum number of characters to be set for other items is as shown below. With Option code /CA, the Descriptor is filled in at the factory as specified in the order.

Item	The Number of Characters
Tag Descriptor Message Date	8 16 32 2/2/2
	T0202.EPS

Example. To change norm ray rendering to the tra	Example:	To change from	Tag YOKOGAWA to	FIC-1A.
--	----------	----------------	-----------------	---------

Call up the **Tag** setting display.

1. Device setup 3. Basic setup 1. Tag	EJA:YOKOGAWA Tag YOKOGAWA YOKOGAWA
	HELP DEL ESC ENTER

F0210.EPS

See Section 2.2.4.

(2) Unit

The unit is set at the factory before shipment if specified at the time of order. Follow the procedure below to change the unit.





(3) Range Change

Ranges are factory-set as specified by the customer. To rerange, change the settings as follows:

(a) Keypad — LRV, URV

Example: To change the range from 0 to 2500 mmH₂O to 500 to 3500 mmH₂O		
EJA: Online 1 Device setup 2 2 Pres 3 A01 Out 4 LRV 5	Select the 4. LRV item.	
2 EJA: 1 LRV 0.0 mmH20 2 URV 2500 mmH20		
HELP HOME	To set the Lower Range Valve, select the LRV item.	
3		
EJA: LRV 0.0 mmH20 0.0	(ENTER)	
HELP DEL ESC ENTER	Enter 500 , and press ENTER (F4) .	
4		
EJA: 1 LRV 500 mmH20 2 URV 3000.0 mmH20		
HELP SEND HOME	To change the Upper Range Valve, select the URV item.	
5		
EJA: URV 2500.0 mmH20 2500.0	'3 5 0 0'	
HELP DEL ESC ENTER	Enter 3500 , and press ENTER (F4) .	
6 EJA: 1 LRV 500.0 mmH20 2 URV 3500.0 mmH20	(SEND)	
HELP SEND HOME	Press SEND (F2) to send the changed data to the transmitter. Check that SEND disappears.	

F0212.EPS

NOTE

It is possible to set LRV > URV. This setting reverses the 4 to 20 mA output signal. Conditions:

 $LSL \leq LRV \leq USL$ $LSL \leq URV \leq USL$ $|URV - LRV| \ge Min.$ Span

The 4 to 20 mA output does not correspond to the scale of the indicator under the following conditions in which:

- · the equipment with standard specification is used with the setting changed to the above setting.
- · the customer specified equipment (with the above factory-setting) is used with the setting changed to the normal (standard) setting.

In the cases above, replace the scale with one which corresponds correctly to the 4 to 20 mA.

(b) Changing the Ranges While Applying an Actual Input — Apply values

This feature allows the lower and upper range values to be setup automatically with the actual input applied. If the upper and lower range values are set, "URV" and "LRV" are changed at the same time.

The measurement span is determined by the upper and lower range valves. Changing the lower range value results in the upper range value change automatically, keeping the span constant.







(4) Output Mode (Linear/Sq root)

The output mode has already been set to a Linear output (Linear). Follow the procedure below to change the mode.

Example: To change the mode from Linear to Sq root.

Call up the Xfer fnctn display.



The output mode is set as specified in the order when the instrument is shipped.

If the instrument is equipped with an integral indicator and Transfer function is sq root, " $\sqrt{-}$ " is displayed on the integral indicator.

E0213.EPS

(5) Damping Time Constants

The damping constant is set to 2.0 seconds at the factory. When changing the damping constant, proceed as follows:

Example: To change from 2.0 seconds to 0.2 seconds

Call up the **Damp** display.





- Only the damping constants listed in Table 2 are available. When a value not listed in Table 2 is entered, the value in Table 2 nearest the entered value is set.
- 2. The damping constant set with the procedure here is of the damping constant in the transmission part (electric circuit). The damping constant of the capsule assembly shall be added to obtain the overall damping constant of the transmitter.

Table 2

0.2 Sec	
0.5 Sec	
1.0 Sec	
2.0 Sec	
4.0 Sec	
8.0 Sec	
16.0 Sec	
32.0 Sec	
64.0 Sec	
T0203 EP	s

(6) Output Signal Low Cut Mode Setup

Low cut can be used on the output signal to stabilize the output near the zero point.

The low cut point can be set in a range from 0 to 20% of output. (Hysteresis of cut point: $\pm 1\%$)

Either **LINEAR** or **ZERO** can be selected as the low cut mode.

Unless otherwise specified, the cut mode is set to LINEAR at the factory.





For low cut in linear mode

Figure 2.2.2 Low Cut Mode



(7) Bi-directional Flow Measurement

(a) **Bi-dir mode** enables selection of 50% output at an input of 0 mmH₂O.



 (b) Combining **Bi-dir mode** with **Xfer fnctn** provides a square root output computed independently for 0% to 50% output and for 50% to 100% output.



Output mode "SQUARE ROOT"

(8) Change Output Limits

The range of normal ouput is preset at factory from -5.0 to 110.0% unless otherwise specified or conditioned, and the output is limited with these upper and lower values. This output range can be changed, for example, to meet the requirements of NAMUR, within the settable range. Set the lower limit with **AO lower limit %** and upper limit with **AO Upper Limit %**.

Settable range : -5.0 to 110.0 (%),

Upper limit > Lower limit

(9) Integral Indicator Display Mode

Example: Change from Linear to Sq root 1. Device setup 4. Detailed setup 4. Display condition 2. Display fnctn EJA: EJA: Display fnctn Linear Linear $\overline{\mathcal{A}}$ Square Root ESC ENTER (ENTER) (SEND) Select Square Root and press ENTER (F4). Press SEND (F2) to send data. F0220.EPS

(10) Integral Indicator Scale

Display Mode	Display	Related Parameters	Description
NORMAL %	455	% rnge 45.6%	Indicates –5 to 110% range depending on the set range (LRV, URV).
USER SET	200	Engr disp range 20.0M	Displays values depending on engr disp LRV and engr disp URV Units set using engr disp unit are not indicated.
USER & %	¥5.6. 200	% rnge 45.6% Engr disp range 20.0M	Indicates user set and % alternately in 3 second intervals.
INP PRES		Pres 456 kPa	Indicates input pressure.
PRES & %		% rnge 45.6% Pres 456 kPa	Indicates input pressure and % alternately in 3 second intervals.

* The number of lines displayed on the LCD is determined by the number of LRV and URV lines set on the brain terminal.

See (a) through (c) for each setting procedure.



(a) Display Mode

Follow the instructions given to the below to change the range of integral indication scale. When **USER SET** is selected, the user set values of integral indication.



(b) Setting User-set Engineering Unit

Engr unit allows entry of the engineering units to be displayed on the HART communicator. When the instrument is shipped, this is set as specified in the order. Follow the procedure below to change this setting.

Since these units are not displayed on the integral indicator, use the adhesive labels provided **Engr unit** need not be set for % display.



(c) Lower and Upper Range Value Setup in Engineering Unit

Engr disp LRV and **Engr disp URV** are used to set the lower and higher range values for the engineering unit display. When the instrument is shipped, these are set as specified in the order. Note that these items need not be set for % display.



(11) Unit for Displayed Temperature

When the instrument is shipped, the temperature units are set to **C** (Centigrade). Follow the procedure below to change this setting.

The unit changed here corresponds the unit for Snsr temp.



(12) Unit for Displayed Static Pressure

Follow the procedure to change the static pressure unit.

Changing this parameter also changes the unit for the static pressure display.



(13) Test Output

This feature can be used to output a fixed current from 3.2 mA (-5%) to 21.6 mA (110%) for loop checks.



- Test output is held for approximately 10 minutes, and then released automatically after the time has elapsed. Even if the HART Communicator power supply is turned off or the communication cable is disconnected during test output, it is held for approximately 10 minutes.
- Press the [4] (OK) key to release test output immediately.

(14) Sensor Trim

Each DPharp EJA Series Transmitter is factory characterized. Factory characterization is the process of comparing a known pressure input with the output of each transmitter sensor module over the entire pressure and temperature operating range. During the characterization process, this comparison information is stored in the transmitter EEPROM. In operation, the transmitter uses this factory-stored curve to produce a process variable output (PV), in engineering units, dependent on the pressure input. The sensor trim calibration procedure allows you to make corrections to the calculated process variable.

There are two ways to trim the sensor: full sensor trim and zero trim. A full sensor trim is a two point process, in which two accurate end-point pressures are applied (equal to or greater than the range values), and all output is linearized between them. A zero trim is a one-point adjustment typically used to compensate for mounting position effects or zero shifts caused by static pressure. (See section 1.1.1)





SPAN adjustment shall be carried out with **Upper Sensor trim**. After selecting **Upper Sensor trim**, apply a pressure of 3000 mmH₂O (corresponding to 100% of the measurement range). Then, proceed the same as for the operations for **Lower Sensor trim**.



(15) Trim Analog Output

Fine output adjustment is carried out with **D/A trim** or **Scaled D/A trim**.

• D/A Trim

D/A trim is to be carried out if the calibration digital ammeter does not read 4.000 mA and 20.000 mA exactly with the output signal of 0% and 100%.

Scaled D/A Trim

Scaled D/A trim is to be carried out if the output is adjusted using a voltmeter or other types of meters or using a meter whose the scale unit is 0 to 100%.



2. HART COMMUNICATOR OPERATION



F0231.EPS

Example 2: To adjust using a voltmeter 1 EJA Trim analog output 3 1 D/A trim 2 Scaled D/A trim Select the Scaled D/A trim item. HELP HOME 2 EJA: WARN-Loop should be removed from automatic control -1 (OK) Press OK (F4). ABORT OK 3 EJA: Trim will be scaled from 4.000 to 20.000 2 1 Proceed 2 Change Select Change, and press ENTER ABORT ENTER (F4). The same operations as for D/A trim are required when selecting item 3. Proceed. 4 '1 EJA Set scale- Lo output IF4 value 4 (ENTER) HELP DEL ABORT ENTER Enter the value read on the meter when the signal is 4 mA. In this case, Enter the value of the voltage across a 250 Ω resistor (1 V), and press ENTER (F4). 5 '5' EJA Set scale- Hi output F4 value 20 20 (ENTER) HELP DEL ABORT ENTER Enter the value read on the meter when the signal is 20 mA. Then, enter 5, and press ENTER (F4). 6 EJA EJA: Trim will be scaled from 1.000 to 5.000 1 Proceed (ENTER) 2 Change Select Proceed and press ENTER ABORT ENTER (F4). 7 EJA: Connect reference meter (OK) Connect the voltmeter, and press ABORT OK OK (F4). 8 EJA: F4 Setting fld dev output to 4mA (OK) Press OK (F4). The output signal of ABORT OK 0% is output. F0232.EPS



(16) Burst Mode

The transmitter continuously sends the data stored in it when the burst mode is set on. Either one of measured pressure variable, % output value, or 4 to 20 mA output value can be selected and sent. The data is sent intermittently as a digital signal at 75 ms intervals when the transmitter is set in the burst mode. Therefore, communication by the HART simultaneous communicator is also possible.

Setting of Burst Mode



F0234.EPS

To Release from the Burst Mode:

Call up the Burst mode display, and set to OFF.

(17) Multidrop Mode

"Multidropping" transmitters refers to the connection of several transmitters to a single communications transmission line. Up to 15 transmitters can be connected when set in the multidrop mode. To activate multidrop communication, the transmitter address must be changed to a number from 1 to 15. This change deactivates the 4 to 20 mA analog output, sending it to 4 mA. The alarm current also is disabled.

Setting of Multidrop Mode





- When the address is set and the multi-drop mode is set to "No" at the same time, Online menus cannot be called up and displayed. Be sure to turn the multidrop mode to "Yes" after setting the address with "Poll addr."
- 2. When the same polling address is set for two or more transmitters in multidrop mode, communication with these transmitters is disabled.

Example: Communication when set in the multi-drop mode

1 HART Communicator Online Decoration Decoration 2 EJA110-2 3 EJA110-3	 (1) The HART communicator searches for the transmitter that is set in the multi-drop mode when the HART communicator is turned on. When the HART communicator is connected to the transmitter, the manufacturer's x'ter type
EJA:EJAl10-1: Online Pres 0.00 mmH20 3 A01 Out .000 mA 4 LRV 0.00 mmH20 5 URM 3500.00 mmH20	 the manufacturer's x ter type code and the tag will be displayed (display 1). (2) Select the desired transmitter. After that, normal communication to the selected transmitter is possible. Howeve
HART Communicator 1 Offline 2 Online 3 Transfer 4 Frequency Device 5 Utility	 the communication speed is slow in this case (display 2). (3) To communicate with another transmitter, turn off the power once and then turn on it again, or call up display 3, and sele online.
	(4) Display 1 will appear. Select the desired transmitter.

To Release the Multi-drop Mode:

Follow the procedure below.

- 1. Call up the **Poll addr** display, and set the address to 0.
- 2. Call up the Auto Poll display, and set to No.

(18) External Switch Mode

• Enabling/inhibiting zero point adjustment using the external zero-adjustment screw on the transmitter. Follow the procedure below to enable or inhibit zero point adjustment from the zero-adjustment screw on the transmitter.

This is set to **ENABLE** when the instrument is shipped.



(19) Software Write Protect

EJA configured data is saved by the write protect function. Write protect status is set to **YES** when 8 alphanumerics are entered in the **New password** field and transferred to the transmitter. In write protect **YES** status, the transmitter does not accept parameter changes. When the 8 alphanumeric string entered in the **New password** field is also entered in the **Enable write** field and transferred to the transmitter, it will be possible to change transmitter parameters during a 10 minute period.

To change the transmitter from Write protect **YES** status back to Write protect **NO** status, enter 8 spaces in the New password field after Write protect has been released using enable write.

(a) Setting Password



(b) Changing the Password



 Enable Wrt 10 min releases Write Protect status for 10 minutes. While Write Protect status is released, enter a new password in the New Password field.

It will not be possible to set a new password when 10 minutes have elapsed.

 To release Write Protect status completely, enter 8 spaces in the New Password field according to the instructions given in (b), Changing the Password. This causes Write Protect status to change from YES to NO.



* "Joker password" and "Software Seal" When you lose the password that has been registered, it is possible to release the mode for 10 minutes by using a joker password. Enter "YOKOGAWA" to release Write protect status for 10 minutes. If this joker password is used, the status shown in the parameter "Software seal" is changed from "Keep" to "Break." Press Hot key and select "2. Wrt Protect menu." Current status is shown in "4. Software seal." This status will be returned from "Break" to "Keep" by registering a new password.

F0240.EPS

(20) Hardware Write Protect and Burnout Direction(with Optional code /F1)

This function prohibits parameter changes through a slide switch on a CPU assembly board. In the case the hardware write protection switch is set to YES, none of the communication method including the handheld terminal such as model 275 is allowed for the alteration of parameters. The write protection switch is factory set to NO(N position in the figure below).





(21) H₂O Unit Select

When mmH₂O, inH₂O or ftH₂O is set, the pressure varies with the standard temperature definition. The Yokogawa default setting for the standard temperature is 4°C (39.2°F). Use the procedure described below when a standard temperature of 20°C ($68^{\circ}F$) is required.

Call up the H_2O Unit select.



2.4 Self-Diagnostics

2.4.1 Checking for Problems

(1) Identify Problems with HART Communicator

Self-diagnostics of the transmitter and check of incorrect data setting can be carried out with the HART communicator. There are two methods for selfdiagnosis of the transmitter, self-diagnosis for every transmission and manually executing the SELF TEST command. When an error message appears, follow "ERROR MESSAGES".

Diagnostic by "self test"



• Error Messages — HART Communicator

Error Message	Probable Cause	Countermeasure
Pressure sensor error	Capsule problem	Replace capsule when error keeps
Temp (Cap) sensor error		after restart.
EEPROM (Cap) failure		
Sensor board not initialized		
Temp (Amp) sensor error	Amplifier problem	Replace amplifier.
EEPROM (Amp) failure		
Dev id not entered		
CPU board not initialized		
Invalid Selection		Change the
Parameter Too High	Set value is too high.	setting.
Parameter Too Low	Set value is too low.	
Incorrect Byte Count		—
In Write Protect Mode	Operation is set in the Write Protect mode.	
Set to Nearest Possible Value	Value is set to a nearest possible value.	_
Lower Range Value too High	LRV set point is too high.	Change the range.
Lower Range Value too Low	LRV set point is too low.	
Upper Range Value too High	URV set point is too high.	
Upper Range Value too Low	URV set point is too low.	
Span too Small	Set span is too small.	
Applied Process Value too High	Applied pressure is too high.	Adjust the applied pressure.
Applied process Value too Low	Applied pressure is too low.	
New LRV pushed URV Over Sensor Limit	The shift of URV according to the new LRV setting exceeds USL.	Change the setting within the range of USL.
Excess Correction Attempted	Amount of correction is too much.	Adjust the amount of correction.
In Proper Current Mode	The fixed current mode is desired but not set in that mode.	Set in the fixed current mode.
In Multidrop Mode	Operation is set in the multi-drop mode.	—

T0205.EPS

(2) Checking with Integral Indicator

If an error is detected in the self-diagnostic, an error number is displayed on the integral indicator. If there is more than one error, the error number changes at twosecond intervals.

See Table 2.4.1 regarding the error numbers.



F0243.EPS

Figure 2.4.1 Identifying Problems Using the Integral Indicator

Integral Indicator Display	Description	Cause	Output Operation during Error	Countermeasure	
None	GOOD				
	ERROR				
Er. 01	CAP MODULE FAULT	Capsule problem ^{*1}	Outputs the signal according to status of burnout direction switch (High or Low).	Replace capsule when error keeps appearing even after resart.*1	
Er. 02	AMP MODULE FAULT	Amplifier problem	Outputs the signal according to status of burnout direction switch (High or Low).	Replace amplifier.	
Er. 03	OUT OF RANGE	Input is outside measurement range limit of capsule.	Outputs high range limit value or low range limit value.	Check input.	
Er. 04	OUT OF SP RANGE	Static pressure exceeds specified range.	Displays present output.	Check line pressure (static pressure).	
Er. 05	OVER TEMP (CAP)	Capsule temperature is outside range (–50 to 130°C).	Displays present output.	Use heat insulation o make lagging to keep temperature within range.	
Er. 06	OVER TEMP (AMP)	Amplifier temperature is outside range (-50 to 95°C).	Displays present output.	Use heat insulation o make lagging to keep temperature within range.	
Er. 07	OVER OUTPUT	Output is outside high or low range limit value.	Outputs high or low range limit value.	Check input and rang setting, and change them as needed.	
Er. 08	OVER DISPLAY	Displayed value is outside high or low range limit value.	Displays high or low range limit value.	Check input and display conditions and modify them as needed.	
Er. 09	ILLEGAL LRV	LRV is outside setting range.	Holds output immediately before error occurrence.	Check LRV and modify as needed.	
Er. 10	ILLEGAL URV	URV is outside setting range.	Holds output immediately before error occurrence.	Check URV and modify as needed.	
Er. 11	ILLEGAL SPAN	SPAN is outside setting range.	Holds output immediately before error occurrence.	Check SPAN and change as needed.	
Er. 12	ZERO ADJ OVER	Zero adjustment is too large.	Displays present output.	Readjust zero point.	

• Error Messages — DPharp Integral Indicator

*1 : This error code appears at capsule problem or when an illiegal overpressure is applied to the pressure sensor.

*2 : If the normal pressure is regained, the Er.01 will disappear according to the setting of the parameter of Auto recover. When the Auto recover is set to ON(default setting), the Er.01 will disappear automatically. When the Auto recover is set to OFF, restart the transmitter to cancel Er.01. If no error code appears then, perform necessary adjustments such as zero-adjustment to continue the operation. If the error code still appears. replace the capsule assembly.

3. PARAMETER LISTS

Item	UHI	Description	Remarks	
	Тад	Tag number	Tag number, Up to 8 characters	
	Descriptor	Descriptor	Up to 16 characters	
	Message	Message	Up to 32 characters	
	Date	Date	xx/yy/zz	
Transmitter	Unit	Unit	inH ₂ O, inHg, ftH ₂ O, mmH ₂ O, mmHg, psi, bar, mbar, g/cm ² , kg/cm ² , Pa, kPa, MPa, torr, atm	
	LRV URV	Lower range value Lower range value	Set the calibration range by the keypad	
	Apply values	Apply values	Range for 4 to 20 mA DC signal is set with actual input applied.	
	Damp	Damping time constant	0.2, 0.5, 1, 1.5, 2, 4, 6, 8, 16, 32 sec	
	Xfer fnctn	Transfer function	linear/Square root	
	Low cut	Low cut	0 to 20 %	
	Cut mode	Cut mode	Linear/Zero	
	Bi-dire mode	Bi-directional mode	On/Off	
	H ₂ O Unit select	H ₂ O Unit select	@4°C/@20°C (68°F)	
	Snsr temp unit	Sensor temperature unit	°C/°F	
	AO lower limit % AO upper limit %	Analog output upper and lower limits	-5.0% to 110.0%	
	Auto recover	Auto recover mode	ON/OFF	
Display	Static pres unit	Static pressure unit	inH ₂ O, inHg, ftH ₂ O, mmH ₂ O, mmHg, psi, bar, mbar, g/cm ² , kg/cm ² , Pa, kPa, torr, atm	
	Display mode	Display mode	Normal % , User set , User set & % , Inp pres , Pres & %	
	Display fnctn	Display fnctn	linear/Square root	
	Engr unit	Engineering unit	Up to 8 characters	
	Engr disp LRV	Engineering display LRV	-19999 to 19999	
	Engr disp URV	Engineering display URV	-19999 to 19999	
	Engr disp point	Engineering display decimal point	0, 1, 2, 3	
HART output	Poll addr	Polling address	1 to 15	
	Auto poll	Auto poll	No/Yes	
	Burst option	Burst mode option	Pres, % rnge, A01 out	
	Burst mode	Burst mode	ON/OFF	
Monitoring	Pres % rnge A01 out Snsr temp Static pres	Pressure variable % output variable 4 to 20 mA output variable Sensor temperature Static pressure	–3.2 mA to 21.6 mA –5.0% to 110.0%	
	Engr display	Output (in Engr unit)	-19999 to 19999	
Mainenance	Loop test	Test output % setting	-5.0% to 110.0%	
	Self test	Self test	Check using the self-test command.	
	Status	Status	Display of the result of self-test, calibration of transmitter.	
	A01 Alarm typ	Status of analog output alarm	High/Low	
	Write Protect	Write Protect	Yes/No	
	Enable Write	Enable Write	8 characters	
	New password	New password	8 characters	
	Ext SW mode	Ext SW mode	Enable/Inhibit	
	Software seal	Software seal	Keep/Break	

T0301.EPS

ltem	UHI	Description	Remarks
Adjustment	Zero trim Zero trim		Set the current input value to 0 kPa.
	Lower sensor trim Upper sensor trim	Lower sensor trim Upper sensor trim	Adjust only measured pressure variable.
	D/A trim Scaled D/A trim	Digital/Analog output trim Scaled D/A trim	Adjust the output value at the points of 4 mA and 20 mA.
Sensor	Isoltr matl	Isolator material	Hast-C, Tantalum, 316L, Unknown, Special
information	Fill fluid	Fill fluid	Silicone oil, F oil, Unknown, Special
	Gasket matl	gasket material	PTFE, 316L, Unknown, Special
	Flange matl	Flange material	Carbon Steel, Hast-C, 316L, Unknown, Special
	Drain vent matl	Drain vent material	316SST, Hast-C, 316L, None, Unknown, Special
	Flange type	Flange type	Conventional, Remote seal, Level, Unknown, Special
	RS isoltr matl	Remote seal isolator material	316 SST, Hast-C, Monel, Tantalum, 316L, Unknown, Special
	Flange size	Flange size	ANSI 150, ANSI 300, ANSI 600, None, Unknown, Special
	Num remote seal	Number of remote seal	One seal, Two seal, None, Unknown
	RS fill fluid	Remote seal fill fluid	Silicone oil, SH704, SH705, Ethy Gly/H ₂ O, Prop Gly/H ₂ O, None, Unknown, Special
	RS type	Remote seal type	Wafer, Nozzle, HTV-W, HTV-N, None, Unknown, Special
Additional information	Distributor Dev type Dev ID Final asmbly num Universal rev Fld dev rev Software rev Model Style LSL USL MIN SPAN Manufacturer Lo snsr trim pt Up snsr trim pt Serial No.	Distributor Device type Device ID Final assembly number Universal revision Fld dev revision Software revision Model Style Lower range limit Upper range limit Minimum span Manufacturer Lower snsr trim pt Upper snsr trim pt Serial Number	YOKOGAWA EJA

REVISION RECORD

Title: Model EJA Series HART Protocol Manual No.: IM 01C22T01-01E

Edition Date	Page	Revised Item
1st Nov. 1995	_	New publication
2nd Mar. 1998	1 3 2-1	 Add EJA-A Series IM numbers to Table 1. Add REVISION RECORD Change the figure of terminal configuration
3rd Mar. 2000	_ 2-19	 Revised a book in a new format. The location of contents and the associated page numbers may not coincide with the one in old edition. 2.3.3(19) • Add Hardware Write Protect and Burnout Direction(with optional code /F1).
4th July 2000	ii 2-6 2-18 3-1	 Add Caution for matching communicator DD and instrument DD. 2.3.2 Add Software seal parameter. Change NOTE for Write Protect. Add software seal
5th Oct. 2000	2-5 2-21	 2.3.1 • Add "MPa" to engineering unit. • Correct the description of Output Operation during Error for Er.01 and Er. 02.
6th Apr. 2003	2-7	2.3.3 • Add Option code /CA.
7th Jan. 2008	-	Miscellaneous corrections.
8th Oct. 2008	2-6 2-10 2-18 2-21 3-1	 2.3.2 Add parameters AO upper/lower limits and Auto recover. 2.3.3 Change the example for a password. 2.4.1 Add descriptions for Er.01 and Auto recover function. 3 Add parameters AO upper/lowerr limits and Auto recover.