


Drawings

MODEL 767401,767402 Pneumatic Pressure Standard

MC100

Unit : mm
(approx. inch)



Note: 1.Be sure to place support beneath the rack where the support will not cover the vent openings on the bottom of the instruments.

2.Provide a clearance of at least 80mm around the instrument for ventilation.

If not specified, the tolerance is ±3%. However, in cases of less than 10mm, the tolerance is ±0.3mm.