
## SICK Sensor Intelligence.

- 1. Insert alignment help into the measurement area of the sensor
- 2. Start alignment mode via display or SOPAS
- 3. Adjust sensor mounting to optimize alignment
- 4. If high gloss material or material fluttering occurs, please angle the sensor approx, minus 8°



## Alignment help

