



### External Dimension

Unit : mm



### Terminal Arrangement



	Terminal No.	Signal
C H 1	1	Contact input (-) (Field side)
	3	Contact input (+) (Field side)
	5	b contact output
	7	a contact output
	9	Common
C H 2	2	Contact input (-) (Field side)
	4	Contact input (+) (Field side)
	6	b contact output
	8	a contact output
	10	Common