


Type code

Type code



Not all variants of the type code can be combined!

Measuring range

	Gauge pressure measuring range		Absolute pressure measuring range		± measuring range
1X0	0 ... 1 bar	1X0	0 ... 1 bar abs	1X0	-1 ... 0 bar
1X6	0 ... 1.6 bar	1X6	0 ... 1.6 bar abs	2X5	-1 ... +1.5 bar
2X5	0 ... 2.5 bar	2X5	0 ... 2.5 bar abs	4X0	-1 ... +3 bar
4X0	0 ... 4 bar	4X0	0 ... 4 bar abs	6X0	-1 ... +5 bar
6X0	0 ... 6 bar	6X0	0 ... 6 bar abs	010	-1 ... +9 bar
010	0 ... 10 bar	010	0 ... 10 bar abs	016	-1 ... +15 bar
016	0 ... 16 bar	016	0 ... 16 bar abs	025	-1 ... +24 bar
025	0 ... 25 bar	025	0 ... 25 bar abs		

	Gauge pressure measuring range
015	0 ... 15 psi
025	0 ... 25 psi
030	0 ... 30 psi
050	0 ... 50 psi
060	0 ... 60 psi
100	0 ... 100 psi
160	0 ... 160 psi
200	0 ... 200 psi
250	0 ... 250 psi
300	0 ... 300 psi

	Absolute pressure measuring range
015	0 ... 15 psi abs
025	0 ... 25 psi abs
030	0 ... 30 psi abs
050	0 ... 50 psi abs
60	1 ... 60 psi abs
100	0 ... 100 psi abs
160	0 ... 160 psi abs
200	0 ... 200 psi abs
250	1 ... 250 psi abs
300	0 ... 300 psi abs

	± measuring range
015	-14.5 ... +0 psi
030	-14.5 ... +15 psi
040	-14.5 ... +25 psi
045	-14.5 ... +30 psi
065	-14.5 ... +50 psi
115	-14.5 ... +100 psi
175	-14.5 ... +160 psi
215	-14.5 ... +200 psi
315	-14.5 ... +300 psi

	Gauge pressure measuring range
X10	0 ... 0.1 MPa
X16	0 ... 0.16 MPa
X25	0 ... 0.25 MPa
X40	0 ... 0.4 MPa
X60	0 ... 0.6 MPa
1X0	0 ... 1 MPa
1X6	0 ... 1.6 MPa
2X5	0 ... 2.5 MPa

	Absolute pressure measuring range
X10	0 ... 0.1 MPa abs
X16	0 ... 0.16 MPa abs
X25	0 ... 0.25 MPa abs
X40	0 ... 0.4 MPa abs
X60	0 ... 0.6 MPa abs
1X0	0 ... 1 MPa abs
1X6	0 ... 1.6 MPa abs
2X5	0 ... 2.5 MPa abs

	± measuring range
X10	-0.1 ... +0 MPa
X25	-0.1 ... +0.15 MPa
X40	-0.1 ... +0.3 MPa
X60	-0.1 ... +0.5 MPa
1X0	-0.1 ... +0.9 MPa
1X6	-0.1 ... +1.5 MPa
2X5	-0.1 ... +2.4 MPa

	Gauge pressure measuring range
1X0	0 ... 1 kg/cm ²
1X6	0 ... 1.6 kg/cm ²
2X5	0 ... 2.5 kg/cm ²
4X0	0 ... 4 kg/cm ²
6X0	0 ... 6 kg/cm ²
010	0 ... 10 kg/cm ²
016	0 ... 16 kg/cm ²
025	0 ... 25 kg/cm ²

	Absolute pressure measuring range
1X0	0 ... 1 kg/cm ² abs
1X6	0 ... 1.6 kg/cm ² abs
2X5	0 ... 2.5 kg/cm ² abs
4X0	0 ... 4 kg/cm ² abs
6X0	0 ... 6 kg/cm ² abs
010	0 ... 10 kg/cm ² abs
016	0 ... 16 kg/cm ² abs
025	0 ... 25 kg/cm ² abs

	± measuring range
1X0	-1 ... 0 kg/cm ²
2X5	-1 ... +1.5 kg/cm ²
4X0	-1 ... +3 kg/cm ²
6X0	-1 ... +5 kg/cm ²
010	-1 ... +9 kg/cm ²
016	-1 ... +15 kg/cm ²
025	-1 ... +24 kg/cm ²